

EXHIBIT C

Sandy -
Leina Higgins
Arco -
213-486-3511

Harry McHosen

Plot Plan

Steve Clifford
Atlantic
497-6729

heavy Mass -

①

Rick - Tank ferro Magnetic finder \$295 for

Detects Iron by
measuring the thickness of the iron

②

6 weeks - 2 months
results can be
inclusive

\$650

Depth
6 (e)

Bruce
Howard

Arco Products Co,
1055 W. 7th St.
P.O. Box 2570
L.A. CA 9005

Fax - 213-486-1282

C 9/29/03
JC

12/4/92

840 ON SITE, AWAITING APT TECH INC
2930 STARTED TEST, PER P. CAFFREY (APT TECH, INC)
AREA LOOKS AS IF REMOVAL HAS BEEN DONE
CONCRETE PADS HAVE BEEN TAKEN OUT AND HAVE
BEEN RECOVERED. THERE SEEM TO HAVE BEEN A
TRENCH DUG OUT BETWEEN AREA WHERE
PUMPS ONCE WERE TO CORNER OF PROPERTY.
THIS WOULD INDICATE VENT LINES FROM TANK AREA

FERRO MAGNETIC DETECTOR

HAND HELD WAND

PROCEDURES SWEEPING MOTION WITH
DETECTOR OVER LOT AREA. IF ANYTHING FOUND
TONE FROM DETECTOR WOULD RING ALERT.

FOUND OIL TANK REAR OF BLDG. - 4" DIAMETER
APPROXIMATELY 500 GAL. L FUEL OIL FOR
HEAT OF CAR WASH

2 DRUMS ARE LOCATED SAME AREA.

4 CONCRETE HATCHES REAR OF BLDG. - FILTERATION T
THEY ARE THE OIL WATER SEPARATION. REW WATER TO
WASH CARS

1 CONCRETE HATCH NEAR OIL TANK + VENT ~ SEPTIC
SYSTEM
THERE IS A VENT (SAME AREA OF TANK)

~~APPROXIMATELY~~ APPROXIMATELY 8' FROM HATCH. THE REMOVED
AND WATER LEVEL INDICATOR WITH COLOR PASTE INTO
CHANGED COLOR

PROBABLY CLEAN OUT VENT — 4 HATCHES

NOTE + A GREEN PASTE THAT TURNS BLUE
WHEN IN CONTACT WITH WATER.

TO SHOCK
ONLY WATER